

Pavement Condition Index (1-10)	
9 - Excellent	6 - Fair
8 - Good	5 - Poor
7 - Good	4 - Poor




Figure No. & Title:
Figure No. 16 - 5 Pavement Condition

Project:
 North Seneca Solar Project

Location:
 Towns of Phelps, Waterloo, & Junius, Ontario & Seneca Counties, NY