# Appendix 16-B Sight Distance Photos at Site Driveways



Entrance #1 - CR 108 Looking Left



Entrance #1 – CR 108 Looking Right

### **Sight Distance Photographs**



Entrance #2 – CR 108 Looking Left



Entrance #2 – CR 108 Looking Right

### **Sight Distance Photographs**



Entrance #3 – Dunham Rd Looking Left



Entrance #3 – Dunham Rd Looking Right

### **Sight Distance Photographs**



Entrance #4 - CR 108 Looking Left



Entrance #4 – CR 108 Looking Right

### **Sight Distance Photographs**




Entrance #5/6 – CR 107 Looking Left




Entrance #5/6 – CR 107 Looking Right

### **Sight Distance Photographs**



Entrance #7 – CR 107 Looking Left



Entrance #7 – CR 107 Looking Right

### **Sight Distance Photographs**



Entrance #8 – CR 107 Looking Left



Entrance #8 – CR 107 Looking Right

### **Sight Distance Photographs**



Entrance #9 – SR 96 Looking Left



Entrance #9 – SR 96 Looking Right

### **Sight Distance Photographs**



Entrance #10 – CR 108 Looking Left



Entrance #10 – CR 108 Looking Right

### **Sight Distance Photographs**



Entrance #11 – SR 96 Looking Left



Entrance #11 – SR 96 Looking Right

### **Sight Distance Photographs**



Entrance #12 – SR 96 Looking Left



Entrance #12 – SR 96 Looking Right

### **Sight Distance Photographs**